





Certificate of Visual Inspection	
<b>PacRim Job Number</b>	16725
<b>Project Name</b>	DC Multiple Projects
<b>Project Address:</b>	930 Tacoma Ave South
<b>Client:</b>	Pierce County Facilities Management
<b>Work Area / Work Completed:</b>	930 building, 6th floor elevator lobby/duct insulation mastic abatement

Following this section is a "Certificate of Visual Inspection". This certification shall be completed by the Contractor and certified by Owner's Consultant. Submit completed Certificate with application for final payment. Final payment will not be made until this certification is executed.

Certificate of Visual Inspection	
In accordance with Section 01577 "Project Decontamination", the Contractor's Certified Supervisor hereby certifies that he has visually inspected the work area (all surfaces, including: pipes, beams, ledges, walls, ceiling and floor, decontamination unit, sheet plastic, etc.) and has found no dust, debris or residue.	
<b>Contractor Printed Name:</b>	Dante Fogarty
<b>Contractor Signature:</b>	
<b>Contractor Title:</b>	Abatement Supervisor
<b>Contractor Signature Date:</b>	11-Oct-2019
<b>Contractor E-mail: (Email Copy to)</b>	

Project Representative Certificate	
Owner's Consultant has accompanied the Contractor on his visual inspection and verifies that this inspection has been thorough and, to the best of his knowledge and belief, the Contractor's certification above is true and accurate.	
<b>PacRim Representative Name:</b>	Tyler Sadler
<b>PacRim Project Representative Signature:</b>	
<b>PacRim Representative Title:</b>	Project Manager
<b>PacRim Representative Signature Date:</b>	11-Oct-2019
<b>Inspection Result:</b>	Pass
<b>Email to: (PacRim):</b>	